
SERVICE KIT

# Accumulator repair kit

**Covers** BRK 55 & BRK 55 VR, all shank sizes · serial no. BGF001432–BGF165129, PN2272023–PN3271330, PUN000001 onward
Numbers match the callouts in the drawing.




**Accumulator repair kit** CP part number **3310101845** Crowder SKU CP-3310101845

## Kit contents

| REF | PART NO. | DESCRIPTION | QTY | NOTES |
|---|---|---|---|---|
| 2 | 3371814052 | Diaphragm | 1 | in the kit; also sold separately |
| 3 | 3371813103 | Charging Screw | 1 | in the kit; also sold separately |
| 4 | 0661100022 | Seal Washer | 1 | in the kit; also sold separately |
| 5 | 3376117071 | Protective Nut | 1 | in the kit; also sold separately |